



MIDWEST ELECTRIC PRODUCTS INC.
305 Gregson Drive Cary, NC 27511

Instruction Bulletin (IBUL)	Drawing: MEPI63
Page 1 of 1	CN: C094002
Subject:	Revision: 03
Customer instruction for C-33 and C-53 angle caps	Created: 02/26/2002

The following is the customer instruction for wiring the C-33 and C-53 angle cap.

**C-33 & C-53
ANGLE CAP**

WIRING INSTRUCTION

NOTICE: Connect only copper or copper clad wire to this device. Cord type: S, SJ, SJO, SO, ST, STO. Wire Size #4 through #10 AWG.

1. Strip outer insulation back 2 inches.
2. Cut black and red wire to 1-1/4 inches long.
3. Strip all wire 5/8 inch long.
4. Remove cap cover. Raise contact blades about 3/4 inch or just enough to insert wires into clamps. Tighten clamp screws to a torque of 20-25 inch pounds.
5. Screw down cord clamp using (2) 7/8-#8 screws and fasten cover securely with (3) 1-1/4-inch-long #4 screws.

MIDWEST ELECTRIC PRODUCTS, INC.
MEPI63 Cary, NC.